




Engineering Services Manager's Report

Engineering and Operations Committee


Item 7b

May 7, 2018

Second Lower Feeder PCCP Rehab - Reach 9



Second Lower Feeder – Reach 9



Earthquake Resistant (SPFC) Steel Pipe Test Section (Courtesy of JFE Steel)



Earthquake Resistant (SPFC) Steel Pipe Examples



