Engineering & Operations Item #6b

Subject: Update on Metropolitan's Seismic Assessment Program

Purpose: To provide an update on the Seismic Assessment Program and

Union Station Headquarters Building Assessment.

Engineering & Operations Item #6b
Summary:

The seismic program is an on going program that evaluates all of MWD's facilities to insure they will provide life safety and continue to operate and deliver water after a major earthquake. The program includes MWD's reservoirs, structures and buildings.



Update on Seismic Assessment & Upgrade Program

Engineering & Operations Committee March 11, 2013

Seismic Program

Goals:


- Provide continuous water deliveries following a major earthquake
- Minimize Damage to Facilities
- Protect Occupants

Drivers:

- Improved knowledge of earthquake probability and seismic forces
- More stringent building codes
- Updated site-specific geotechnical information

Origin of the Seismic Program

Jensen Plant Construction -1971





Over \$3 million Damage from Sylmar Earthquake


Examples of Changes to Peak Ground Accelerations Over Time at Weymouth

Year	Design Peak Ground Acceleration (PGA)
1933	0.1g
UBC 1988	0.4g
UBC 1994	0.4g
UBC 1997	0.52g
IBC 2009	0.71g


Seismic Program Components

- Buildings & Structures
- Dams & Reservoirs
- Geotechnical Hazards






Program Methodology for Structures



Status of Seismic Upgrades




Hinds Pumping Plant - 1996

Hinds Pumping Plant



Slope Stabilized by Roller Compacted Concrete



Analytical Tools

- Structural Analysis
- Soil Analysis
- Hydraulic Analysis
- Surveying
- CAD



Santa Ana Bridge


- Seismic Issues
 - Base isolators to be replaced
 - Existing piers need to be reinforced
 - Existing truss to be evaluated



- Board Action Item 7-5
 - Procurement of base isolators


Sepulveda Canyon Control Facility

- Seismic Issues
 - Potential settlement under east tank
 - Potential settlement under hydroelectric plant
 - Strengthening of structures required
- Current Action Item 7-1
 - Geotechnical assessment and modeling of slope



3D Geotechnical Analysis

Sepulveda Canyon Control Facility




Deformation Mesh with 20x exaggeration

3D Survey Capability

- Fast and efficient
- Accuracy within 1/8"
- Can be converted into 3D CAD model



3D Graphic Capability



Update on Headquarters Building



Background

- Development agreement with Union Station Partners
- Deficiencies identified from 2008 to 2012
- Several repairs performed to date




Background

- Preliminary
 Assessment
 - Preliminary assessment initiated 2010
 - Findings verified by specialty consultant in 2011
 - Several support beams have large openings




Union Station Structural Modeling





Work in Progress

- 1. Material tests completed
 - Concrete strength 30% greater than design value
- 2. Geotechnical analysis completed
- 3. Structural component tests underway
 - Test lab UC Irvine
 - Phase 1 Existing beam testing Presently underway
 - Phase 2 Retrofitted beam tests April 2013



Assembly of Test Beams








Remaining Tasks

- 4. Advanced nonlinear structural analysis
 - Structural model completed by specialty consultant
 - Adjust model beam properties based on component test results
- 5. Determine seismic performance level of existing structure
- 6. Future Board Action:
 - Authorize final design of upgrades



Project Schedule

